



UNITED STATES DEPARTMENT OF COMMERCE
Patent and Trademark Office
ASSISTANT SECRETARY OF COMMERCE AND
COMMISSIONER OF PATENTS AND TRADEMARKS
P.O. Box 1450
Alexandria, VA 22313-1450

December 1, 2010

**Townsend and Townsend and Crew LLP /Pulmonx 017534
Two Embarcadero Center, Eighth Floor
San Francisco CA 94111-3834**

Patent No. : 7,798,147 B2
Inventor(s) : Michael Hendrickson, et al.
Issued : September 21, 2010
For : **BRONCHIAL FLOW CONTROL
DEVICES WITH MEMBRANE SEAL**
Doc. No.: 017534-005301US

To Whom It May Concern:

The Certificate of Correction issued on November 30, 2010, issued in error, in that error(s) was made in identifying the patent number and/or keying text/corrections, i.e.:

The column and line number identifying location of error in patent was not printed in the issued cofc. The correction displays "Claim 50", listing claim number. The correction should be shown as --Column 23, line 60-Column 24, line 22, Claim 50 should read--. A new certificate of correction will be issued listing the Column and line number location where error appears in the printed patent.

Therefore, a certificate of correction will be issued to correct (supersede) the Certificate of Correction containing error(s), made during preparation of the Certificate of Correction, as noted above.

No further response is required, from applicants (attorney). However, errors discovered by attorney, other than as noted and described above, should be noted on *a copy* of the Certificate of Correction that was issued in error, accompanied by a signed transmittal letter and submitted directed to this Branch.

Antonio Johnson
(571)272-0483
For Mary F. Diggs, Supervisor
Decisions & Certificates of Correction Branch
(703) 756-1580